

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 08/06/2026

It is certified that the existing building (name of the building or premises) at Max Baseliious Public School, Devalokam, Kottayam (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Two	Two	Two	Two	Two	

The building is owned/occupied by Max Baseliious Public School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on 08/06/2026 (date of inspection) in the presence of (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 08/06/2026 at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department/ Office: _____


08/06/2026

Dr. BINU M. ISSAC Ph.D., M.Tech, MIE, FIV.
Chartered Engineer, Approved Valuer
&
Structural Consultant


AALAYA
CIVIL ENGINEERING SERVICES
2nd Floor, Adam Tower,
Star Junction, Kottayam-686 001
E-mail: binumissac@yahoo.com

FITNESS CERTIFICATE

1	Name of the School	Mar Baselious Public School			
2	Location	Devakolam, Kottayam, Kerala.			
3	Education District and Sub District	Kottayam / Kottayam			
4	Building Number	10/318 of Vijayapuram Grama Panchayath			
5	Classification of building as specified in the application for fitness	Permanent R C C framed structure			
6	Building name	No of Floors	Total Plinth area in m²	Height of Each floor in m	Year of Construction
	Block I	2	2922	3.6	2004
	Block V	2	2922	3.6	2004
	Block IV	2	1336	3.6	2008
	Block III	2	3080	3.6	2010
	Block II	2	2412	3.6	2013
7	Period for which certificate is issued	For 5 Years			
8	Nature of defects if, any				
	i. Foundation and basement	No visible defects.			
	ii. Superstructure	No visible defects.			
	iii. Doors and Windows	No visible defects.			
	iv. Wood work wrought up and put up	No visible defects.			
	v. Roof	No visible defects.			
	vi. Flooring	No visible defects.			
	vii. Miscellaneous (cracks etc.)	No visible defects.			
9	Whether maintenance works have been done properly	Yes.			
10	Whether the structure is sound for conducting classes	Yes.			

CERTIFICATE

Certified that the school building was inspected on 08/06/2026 and found to be fit to conduct classes for a period of five years for the reasons stated above.


08/06/2026.
Dr. BINU M. ISSAC; M.Tech; Ph.D; MIE; FIV.
Chartered Engineer & Structural Consultant
AALAYA CIVIL ENGINEERING SERVICES
Adam Tower, Star Junction, Kottayam - 686 001